

Windmill Overdrive

PedalPCB.com

Bag 1

Resistor 130R	1
Resistor 1k	1
Resistor 3,3k	6
Resistor 4,7k	1
Resistor 10k	1
Resistor 12k	3
Resistor 62k	1
Resistor 100k	2
Resistor 200k	1
Resistor 1M	1
Resistor 10M	2
Zener 9,1V 0,5W	3
1N5817	1

Bag 2

Keramik 270pF	1
Keramik 470pF	1
MKT 2,2nF	2
MKT 4,7nF	1
MKT 10nF	2
MKT 47nF	1
MKT 0,1uF	2
MKT 0,22uF	1
MKT 0,47uF	1
Elko 4,7uF	1
Elko 10uF	2
Elko 100uF	4

Bag 3

3 Pin socket	2
BS170	3
LED 5mm red	1
LED bezel 5mm	1

Bag 4

Potentiometer 16mm 500k lin vert. pcb	1
Potentiometer 16mm 100k log vert. pcb	1
Potentiometer 16mm 500k log vert. pcb	2
Bumper 12,7mm (back of pots)	4
6,3mm phone jack mono Lumberg	2
Bumper transparent	1
DC jack isolated	1
Footswitch 3PDT	1

Wire pack	1
PCB Windmill Overdrive	1
3PDT Breakout Board	1