

## Klone Centaur

PCB Guitar Mania

### Bag 1

Resistor 22R	1
Resistor 470R	1
Resistor 1k	3
Resistor 1,5k	2
Resistor 1,8k	1
Resistor 2k	1
Resistor 4,7k	2
Resistor 5,1k	1
Resistor 10k	1
Resistor 12k	1
Resistor 15k	2
Resistor 22k	1
Resistor 27k	1
Resistor 47	1
Resistor 100k	2
Resistor 390k	1
Resistor 422k	1
Resistor 1M	1
Resistor 2,2M	1
1N5817	1
OA1182 (=1N34A)	2
Zener 12V 0,5W	1

### Bag 2

Ceramic disc 220pF	1
Ceramic disc 390pF	1
MKT 1nF	1
MKT 2,2nF	1
MKT 3,9nF	1
MKT 27nF	1
MKT 68nF	2
MKT 82nF	1
MKT 0,1uF	3
MKT 0,39uF	1
MKT 1uF	4
Elko 10uF	2
Elko 100uF	1

### Bag 3

8 Pin IC socket	3
TC1044S	1
TL072	2
LED 5mm red	5
LED bezel 5mm chrome	1

### Bag 4

Poti 16mm 10k log vert. pcb	1
Poti 16mm 10k lin vert. pcb	1
Poti 16mm 100k lin Stereo vert. pcb	1
Toggle switch SPDT	1
Bumper 12,7mm (back of pots)	2
6,3mm phone jack mono	2
Bumper	1
DC jack isolated	1
Footswitch 3PDT	1

Wire bag	1
PCB Klone Centaur	1
3PDT Board	1