

Chauffeur Overdrive

PedalPCB.com

Bag 1

Resistor 100R	1
Resistor 330R	1
Resistor 470R	1
Resistor 1k	7
Resistor 4,7k	3
Resistor 6,2k	1
Resistor 10k	2
Resistor 12k (=12,4k)	1
Resistor 15k	1
Resistor 22k	4
Resistor 47k	2
Resistor 100k	1
Resistor 560k (=576k)	1
Resistor 1M	1
Zener 0,5W 2,7V (=2,5V)	4
Zener 0,5W 5,1V	1
Zener 0,5W 12V	1
1N4148	1
1N4007	2
1N5819	1

Bag 2

Keramik 47pF	1
Keramik 150pF	3
MKT 2,2nF	1
MKT 3,3nF	1
MKT 4,7nF	1
MKT 8,2nF	1
MKT 15nF	1
MKT 27nF	1
MKT 33nF	1
MKT 47nF	1
MKT 0,1uF	5
MKT 0,47uF	2
MKT 1uF	1
Elko 22uF	7
Elko 47uF	9
Elko 100uF	2

Bag 3

2N4401	2
2N4403	1
3 Pin Socket	1
ICL7660S	1
RC4558	1
8 Pin IC Socket	6
LED 5mm red	1
LED bezel 5mm	1

Bag 4

Poti 16mm 10k lin vert. pcb	4
Bumper 12,7mm (back of pots)	4
Toggleswitch 1x on-off-on	1
6,3mm phone jack mono Lumberg	2
Bumper transparent	1
DC jack isolated	1
Footswitch 3PDT	1

Wire pack	1
PCB Chauffeur Overdrive	1
3PDT Breakout Board	1