

Dirt Dauber Sub-Octave Fuzz

PedalPCB.com

Bag 1

Resistor 2,2k	1
Resistor 4,7k	2
Resistor 100k	2
Resistor 3,3M	2
1N5817	1

Bag 2

MKT 0,1uF	4
Elko 1uF	2
Elko 100uF	1

Bag 3

16 Pin IC Socket	2
CD4049U	1
CD4040	1
LED 5mm rot	2
LED Clip 5mm	2

Bag 4

Potentiometer 16mm 100k lin vert. pcb	2
Potentiometer 16mm 100k log vert. pcb	1
Bumper 12,7mm (back of pots)	3
Kippschalter SPDT	1
6,3mm phone jack mono	2
Bumper transparent	1
DC jack isolated	1
Footswitch 3PDT	1

Wire pack	1
PCB Dirt Dauber Sub-Octave Fuzz	1
3PDT Breakout Board	1