

**Glue Factory Overdrive**

PedalPCB.com

## Bag 1

Resistor 100R	1
Resistor 220R	1
Resistor 1k	5
Resistor 4,7k	1
Resistor 10k	8
Resistor 510k	2
Resistor 1M	1
1N4148	2
1N5817	1

## Bag 2

Keramik 51pF	1
MKT 27nF	1
MKT 0,1uF	2
MKT 0,22uF	3
MKT 1uF	2
Elko 10uF	1
Elko 47uF	2

## Bag 3

8 Pin IC socket	1
RC4558	1
2N3904	2
3 Pin Socket	2
LED 5mm red	1
LED bezel 5mm	1

## Bag 4

Potentiometer 16mm 1M log vert. pcb	1
Potentiometer 16mm 5k lin vert. pcb	1
Potentiometer 16mm 100k lin vert. pcb	1
Toggleswitch SPDT	1
Bumper 12,7mm (back of pots)	3
6,3mm phone jack mono Lumberg	2
Bumper transparent	1
DC jack isolated	1
Footswitch 3PDT	1

Wire pack	1
PCB Glue Factory	1
3PDT Breakout Board	1