

**Stockade Overdrive**

PedalPCB.com

## Bag 1

Resistor 100R	2
Resistor 330R	1
Resistor 1k	6
Resistor 4,7k	4
Resistor 10k	8
Resistor 22k	2
Resistor 100k	1
Resistor 560k	2
Resistor 1M	2
Resistor 10M	1
1N916	3
1N4148	4
BAT41	2
Zener 1,8V 0,5W	2
1N5817	1

## Bag 2

Keramik 47pF	1
Keramik 100pF	1
MKT 33nF	1
MKT 68nF	2
MKT 0,1uF	3
MKT 0,15uF	1
MKT 0,22uF	1
MKT 0,33uF	1
MKT 0,47uF	1
MKT 1uF	5
Elko 2,2uF	1
Elko 10uF	2
Elko 47uF	1
Elko 100uF	1

## Bag 3

LM833	1
MPSA18	2
MPSA13	1
2N7000	2
8 Pin IC socket	1
3 Pin socket	5
LED 3mm red	3
LED 5mm red	3
LED Clip 5mm	3

## Bag 4

Poti 16mm 5k lin vert. pcb	1
Poti 16mm 100k lin vert. pcb	2
Poti 16mm 1M lin vert. pcb	1
Poti 16mm 500k log vert. pcb	1
Bumper 12,7mm (back of pots)	5
Toggleswitch SPDT	2
Rotary Switch 1P8T	2
6,3mm phone jack mono Lumberg	2
Bumper transparent	1
DC jack isolated	1
Footswitch 3PDT	3
Wire pack	1
PCB Stockade Overdrive	1