

**Thunder Pipe Fuzz**

PedalPCB.com

## Bag 1

Resistor 100R	2
Resistor 390R	2
Resistor 1k	1
Resistor 1,8k	1
Resistor 3,3k	1
Resistor 4,7k	1
Resistor 10k	4
Resistor 12k	4
Resistor 47k	1
Resistor 56k	1
Resistor 100k	4
Resistor 470k	5
Resistor 2,2M	1
D9E	1
1N914	2
1N5817	1

## Bag 2

Keramik 470pF	3
MKT 3,3nF	1
MKT 6,8nF	1
MKT 47nF	2
MKT 0,1uF	10
MKT 1uF	1
Elko 100uF	1

## Bag 3

MPS2222	2
2N5089	3
3 Pin Socket	5
LED 5mm red	1
LED bezel 5mm	1

## Bag 4

Poti 16mm 100k lin vert. pcb	2
Poti 16mm 250k lin vert. pcb	2
Poti 16mm 100k log vert. pcb	2
Bumper 12,7mm (back of pots)	2
6,3mm phone jack mono Lumberg	2
Bumper transparent	1
DC jack isolated	1
Footswitch 3PDT	1

Wire pack	1
PCB Thunder Pipe Fuzz	1
3PDT Breakout Board	1